



46TH TURBOMACHINERY & 33RD PUMP SYMPOSIA
HOUSTON, TEXAS | DECEMBER 11-14, 2017
GEORGE R. BROWN CONVENTION CENTER

Gas turbine with rotor crack vibration diagnostics



Dipl. Ing. Peter Popaleny, PhD.

Technical Leader, West Europe
Machinery Diagnostics Services
GE Bently Nevada
peter.popaleny@ge.com



Dipl. Ing. Nicolas Péton


Global Director
Machinery Diagnostics Services
GE Bently Nevada
nicolas.peton@ge.com

Abstract

The case study describes rotor crack detection using vibration measurements, documented on real case of heavy duty Gas Turbine. The study highlights the complexity of rotor crack diagnostics as the primary problem as it can be often masked by other existing machine malfunctions, such as unbalance, misalignment, bearing looseness or soft foot. The presentation describes the detected symptoms of rotor crack: increase of rotor bow demonstrated by changes in slow roll vectors, decrease in rotor modal stiffness demonstrated by decrease in resonance frequency, the decrease in effective damping, appearance of the split resonance in the rotor shut down not present during the start up, the unidirectional changes in the rotor bow and the repeatability of abnormal-unidirectional rotor response.



Machine train: Gas Turbine - Generator



BRG1X BRG1Y



BRG 1

BRG2X BRG2Y



BRG 2

BRG3X BRG3Y



BRG 3

BRG4X BRG4Y



BRG 4

BRG5X BRG5Y



BRG 5

The machine train consists of a single-shaft heavy duty Gas Turbine (120MW, 3000rpm, in service since 1998) directly rigidly coupled on hot end to a synchronous generator. The compressor portion of the gas turbine rotor consists of stacked blade wheels held with tiebolts and it is connected to the turbine rotor via marriage joint. The turbine rotor consists of three turbine wheels with buckets held together with through bolts. The rotor is supported by three main journal bearings (BrG.1,2 Elliptical, BrG.3 tilting pad).





History / Scope of the job

- History none – no permanently installed diagnostics system
- Control System on site with direct trends only
- High vibration during start up – machine trip
- Scope of the job - balancing



First Start up



During Start up, the unit reached the trip levels at bearing 1 vertical seismic transducer (28.8mm/s pk) at 2221rpm and was tripped manually.



First Conclusions

- the coupling balancing is suggested in the first step to pass the resonance
- after unit can pass the critical speed the next evaluation of the alignment for machine hot conditions is recommended.
- bearing 3 looseness, soft foot suspected



First Step: Balancing

Date	Start Up No.	Bal. Run	Weight Installed	Weight Removed	Resultant W for calculation	Weight on Generator Brg5 couplin Balancing Plane	Weight on Generator Brg4 couplin Balancing Plane	Weight on GT Brg1 aux. coupling Balancing Plane	Note Load 0deg Reference Brg1V transducer
JUN16	SU3	1	-	803g@0	-		-		Repeated Original Run, FSNL, 3000rpm
JUN16	SU4	3	1030g@45	-	1030g@45		H2:555g H16:560g	-	Calibration Run2, trip at 2075rpm
JUN16	SU5	4	339g@297	1030g@45	339g@297		-	H15:339g	Calibration Run3,
JUN17	SU6	5	350g@180	339g@297	350g@180		H7:350g=175g+175g		Calibration Run4, FSNL+7min
JUN17	SU7	5	350g@180		350g@180		H7:350g=175g+175g		Repeated Calibration Run4, FSNL+12min
JUN17	SU8	6	304g@0	350g@180	304g@0	H22:304g=147g+157g			Calibration Run5, FSNL+12min
JUN18	SU9	7	412g@94 591g@255	304g@0	412g@94 591g@255		close to H3:412g H15:591g=191g+205g+195g		Correction Run1, KPH lost after FSNL
JUN18	SU10	7	413g@94 591g@255		413g@94 591g@255		close to H3:413g=238g+175g H15:591g=191g+205g+195g		Repeated Correction Run1
JUN24	SU11	7	413g@94 591g@255		413g@94 591g@255		close to H3:413g=238g+175g H15:591g=191g+205g+195g		Repeated Correction Run1 after generator anchor bolts torque correction and Brg3 soft foot correction




Table of balancing weights placement history

Balancing - Generator balanced



The Generator successfully balanced and the 1X vibration levels on the Generator bearings are in Zone A, according to the ISO 10816-4.

Next: Brg.3 looseness, soft foot check



Bearing Metal temperatures at FSNL:

Brg1=50-52deg C

Brg2=68-70deg C

Brg3=48-49deg C

Brg4=76-72deg C

Brg5=68-68deg C

SCL position in bearing 3,4 abnormally low, metal temp low suggest misalignment Brg 3 orbit shape, extreme size and vertical orientation may be due to lowered stiffness and bearing 3 looseness or soft foot

Brg.3 looseness, soft foot




Gas Turbine Bearing 3 base plate shims moved, after reinstalling same height shims, Brg3 base plate raised 200/250um left/right

What was done

- Bearing 3 opened, clearances were checked
- Alignment Gas Turbine – Generator was performed
- Gas Turbine soft foot check performed on all the foots
- Bearing 1 opened, clearances were checked




Comparison of 1X, SU/SD6 and SU/SD7



difference in critical speed between SU and SD, repeatable SU and repeatable SD
small change in slow roll




Comparison of 1X, SU/SD10 and SU/SD11



difference in critical speed between SU and SD, repeatable SU and repeatable SD
small change in slow roll (6-14umpp), and split resonance appeared




Comparison of 1X, SU/SD10 and SU/SD11



small change in slow roll (6-14umpp)
unidirectional change



Comparison of 2X, SU/SD10 and SU/SD11




2X component NOT greatly amplified at half of resonance
2X amplified at critical speed is due to Nonlinear Stiffness




Steady State 1X, SU/SD10 and SU/SD11

BRG1X 113 um pp /178° 2811 rpm 18JUN2014 11:57:59.991
Gas Turbine From 18JUN2014 11:58:00 To 18JUN2014 12:20:00
BRG1X 107 um pp /150° 2945 rpm 24JUN2014 09:42:59.885
Gas Turbine From 24JUN2014 09:43:00 To 24JUN2014 10:00:00



500 um pp FULL SCALE

BRG3X 175 um pp /303° 2811 rpm 18JUN2014 11:57:59.991
Gas Turbine From 18JUN2014 11:58:00 To 18JUN2014 12:20:00
BRG3X 162 um pp /304° 2945 rpm 24JUN2014 09:42:59.885
Gas Turbine From 24JUN2014 09:43:00 To 24JUN2014 10:00:00



CCW ROTATION 500 um pp FULL SCALE

CCW ROTATION

repeatable unidirectional change of 1X vector





Conclusion - Possible Rotor Crack

- Modified original slow roll rotor response – NOT significant (6-14umpp) in our case
- Unidirectional changes in the rotor bow
- Decrease in rotor modal stiffness demonstrated by decrease in resonance frequency
- Decrease in effective damping demonstrated by higher Synchronous Amplification Factor (SAF)
- Appearance of the split resonance in the rotor start up and shut down data and increase of their span may indicate a pending crack on the rotor [40]. The split resonance during the shutdown, not present during the startup, may suggest the crack propagation.
- Abnormal rotor thermal and load sensitivity – NOT tested on load, only FSNL
- Repeatability of abnormal-unidirectional rotor response



Gas Turbine Rotor Crack - confirmed



180deg circumferential crack detected, 18mm deep

at the Turbine forward stub shaft, at the marriage joint near the bearing 2

absence of 2X can be possibly explained by lack of radial preload to open the crack, due to vicinity of bearing 2.



End



The case story further showed the difficulty of detecting the rotor crack as primary problem as it can often be masked by other existing machine malfunctions.